

## Infinitum Inverter FW 4.4 Release Notes

### v4.4.0 Release notes

Added the MAX acceleration and MAX deceleration registers back into the code.

Fixed the deceleration issue, where the deceleration was not being used correctly and causing OverVoltage. Acceleration was being used for both.

Fix the delay in Factory Settings response to CIM.

Move location of 18V check to after the Factory settings load instead of before the factory settings load.

Fixed startup fault when run command is active immediately after a power cycle.

v4.3.0 Partial Fix for the deceleration issue, where the deceleration was not being used correctly and causing OverVoltage.

v4.2.0 Added the MAX acceleration and MAX deceleration registers back into the code.

V4.1.0 Add the register to select RTD or Thermistor Temperature from the stator.